



HUMAN FACTORS




1 Lack of communication




2 Complacency



3 Lack of knowledge



4 Distraction



5 Lack of teamwork



6 Being tired (Fatigue)




7 Lack of resources




8 Pressure



9 Lack of assertiveness



10 Stress



11 Lack of awareness



12 Norms
(Convention, Standards)

All of these can affect your work



JOINT INSPECTION GROUP

Save & share
this poster



HSSE

